



SCALE IN FEET

Treatment Alternatives Key

- A - No Action
- B - Vegetation Only
- C - Repair Protection
- D - Vegetate Structure
- E - Remove Structure
- F - Regrade and Replant
- G - Terrace
- H - Riprap Toe
- I - Vegetated Riprap
- J - Vegetated Wall

Zone	Station Point	Clear Feet	Stabilization/Revegetation Recommendation	Ownership Summary
254	N327+95 to 328+05	10	C	Private
255	N328+50 to 327+95	115	A or B	Private
256	N328+05 to 327+35	230	J	Private
257	N330+35 to 330+45	10	C	Private
258	N330+45 to 331+40	95	A	Private
259	N331+40 to 331+50	10	C	Private
260	N331+50 to 332+00	60	J	Private
261	N332+70 to 333+25	95	A or B	Private
262	N332+00 to 334+80	230	A	Private
263	S335+15 to 335+30	15	C	Stanford
264	N334+30 to 346+95	12660	J	Private
265	N338+35 to 338+80	45	A or B	Private
266	S335+30 to 344+85	950	A, B, F, G, I or J	Stanford

Indicates a high priority stabilization project

See Sheet 15

- Key**
- Existing path/trail at top of bank.
 - Opportunity for new path at top of bank.
 - Opportunity for overlook.
 - Opportunity for small pocket park.
 - Opportunity for interpretive panel site.
 - Add creek identification at road crossing.

See Sheet 13

14

BANK STABILIZATION AND REVEGETATION RECOMMENDATIONS

SAN FRANCISCO CREEK
BANK STABILIZATION & REVEGETATION
PRELIMINARY MASTER PLAN REPORT

Station: 326+00 to 339+00 September, 2000