



- Treatment Alternatives Key**
- A - No Action
 - B - Vegetation Only
 - C - Repair Protection
 - D - Vegetate Structure
 - E - Remove Structure
 - F - Regrade and Replant
 - G - Terrace
 - H - Riprap Toe
 - I - Vegetated Riprap
 - J - Vegetated Wall

Indicates a high priority stabilization project

Zone	Station Point	Linear Feet	Stabilization/Revegetation Recommendation	Ownership Summary
276	N364+65 to 356+65	200	A	Private
277	S354+85 to 355+40	55	A	Stanford
278	S355+15 to 355+80	65	A or B	Stanford
279	S355+75 to 357+00	125	A	Stanford
280	N356+50 to 356+95	45	A or B	Private
281	N356+65 to 358+70	205	A or J	Private
282	N356+90 to 358+70	180	A or C	Private
283	S356+80 to 359+05	225	A or B	Stanford
284	S358+70 to 359+90	120	A	Stanford
285	N358+70 to 359+00	30	C	Private
286	N359+80 to 360+35	55	A or B	Private
287	S359+90 to 361+20	130	E and J	Stanford
288	N359+00 to 361+40	240	A	Private
289	N360+90 to 362+30	140	A or B	Private
290	N362+20 to 363+90	170	A	Private
291	S361+20 to 368+40	720	I or J	Private
292	N363+90 to 368+55	465	J	Private
293	N366+10 to 367+85	175	A or B	Private
294	N368+55 to 370+65	210	A or B	Private
295	N368+55 to 370+75	220	C or (E and J)	Stanford
296	S368+40 to 372+35	395	A	Stanford

- Key**
- Existing path/trail at top of bank.
 - Opportunity for new path at top of bank.
 - Opportunity for overlook.
 - Opportunity for small pocket park.
 - Opportunity for interpretive panel site.
 - Add creek identification at road crossing.

16

**BANK STABILIZATION AND
REVEGETATION RECOMMENDATIONS**

SAN FRANCISCO CREEK
BANK STABILIZATION & REVEGETATION
PRELIMINARY MASTER PLAN REPORT

Station: 354+00 to 371+00 September, 2000

See Sheet 17

See Sheet 15