See Sheet 18




Key

- Existing path/trail at top of bank.
- Opportunity for new path at top of bank.
- O Opportunity for overlook.
- P Opportunity for small pocket park.
- ✱ Opportunity for interpretive panel site.
- ✱ Add creek identification at road crossing.

| Zone | Station Point | Linear Feet | Stabilization/ Revegetation Recommendation | Ownership Summary |
|---|---|---|---|---|
| 297 | N370+75 to 371+25 | 50 | J | Private |
| 298 | S372+00 to 372+80 | 80 | A or B | Stanford |
| 299 | N371+55 to 373+85 | 230 | A | Private |
| 300 | N372+15 to 376+00 | 385 | A or B | Private |
| 301 | N374+40 to 381+00 | 660 | A | Private |
| 302 | S372+35 to 380+00 | 765 | A | Stanford |
| 303 | S380+00 to 380+30 | 30 | C | Stanford |
| 304 | N381+45 to 381+80 | 35 | C | Private |
| 305 | N381+60 to 382+70 | 110 | A or D | Private |
| 306 | S380+75 to 382+60 | 185 | A | Stanford |
| 307 | S382+50 to 383+10 | 60 | A or (E and B) | Stanford |
| 308 | N382+75 to 392+65 | 990 | A | Private |
| 309 | S382+85 to 386+20 | 335 | A | Stanford |
| 310 | S383+30 to 386+00 | 270 | A or (E and B) | Stanford |
| 311 | N386+15 to 387+00 | 85 | A or F | Stanford |

Indicates a high priority stabilization project

Treatment Alternatives Key

- A – No Action
- B – Vegetation Only
- C – Repair Protection
- D – Vegetate Structure
- E – Remove Structure
- F – Regrade and Replant
- G – Terrace
- H – Riprap Toe
- I – Vegetated Riprap
- J – Vegetated Wall

See Sheet 16



# BANK STABILIZATION AND REVEGETATION RECOMMENDATIONS

SAN FRANCISQUITO CREEK
BANK STABILIZATION & REVEGETATION
PRELIMINARY MASTER PLAN REPORT

Station: 371+00 to 387+00 September, 2000